

005120" F440560




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

005443.03500




FIG. 7

0504431.021500




FIG. 8




FIG. 9






FIG. 10

GOP INDEX	ECC addr.	ECC blk.No.	I-Pic blk.No.	Start Frm	End Frm	Audio Offset	Audio ECC
9	280	12	2	1	15	11	1
10	292	13	3	1	15	12	1
11	305	13	3	1	15	12	1
...							
34	617	12	2	1	15	11	1
35	629	12	2	1	15	11	1

FIG. 11

GOP INDEX	ECC addr.	ECC blk.No.	I-Pic blk.No.	Start Frm	End Frm	Audio Offset	Audio ECC
9	280	12	2	1	15	11	1
10	292	13	3	1	4	12	1
35	629	12	2	13	15	11	1

FIG. 12

I1 B2 B3 P4 B5 B6 P7 B8 B9 P10 B11 B12 P13 B14 B15

FIG. 13




FIG. 14

005120" FE40550




FIG. 15




FIG. 16




FIG. 17




FIG. 18

SYSTEM HEADER	(GOP1) ECC BLOCK ADDRESS:1 NUMBER OF ECC BLOCKS:10 NUMBER OF I-PICTURE BLOCKS:2	(GOP2) ECC BLOCK ADDRESS:11 NUMBER OF ECC BLOCKS:10 NUMBER OF I-PICTURE BLOCKS:3	(GOP3) ECC BLOCK ADDRESS:21 NUMBER OF ECC BLOCKS:11 NUMBER OF I-PICTURE BLOCKS:2
------------------	--	---	---

FIG. 19




FIG. 20




FIG. 21

STEREOPHONIC 1 CHANNEL

L,R	STUFFING
-----	----------

FIG. 22A

STEREOPHONIC 2 CHANNELS

L1,R1	L2,R2
-------	-------

FIG. 22B

MONOPHONIC

JAPANESE	STUFFING
----------	----------

FIG. 22C

SUBVOICE

JAPANESE	ENGLISH
----------	---------

FIG. 22D